# **Newberry Springs FD**


Newberry Springs, CA


This report was generated on 9/19/2024 2:45:40 PM



### Major Incident Types by Month for Date Range

Start Date: 08/01/2024 | End Date: 08/31/2024





INCIDENT TYPE	AUG	TOTAL
False Alarm & False Call	1.00	1
Fire	3	3
Good Intent Call	2	2
Hazardous Condition (No Fire)	1	1
Rescue & Emergency Medical Service Incident	25	25
Service Call	3	3
Special Incident Type	1	1
Total	36	36



## NEWBERRY SPRINGS FIRE DEPT.

## MONTHLY REPORT AUGUST- SEPTEMBER 2024

\*TRAINING IN HOUSE: 10 Hours. Individual FireFighters Online Computer Training- (4) Hours.

- A. Medical / trauma bags and fire apparatus checked out weekly.
- B. Firefighter task books (for FF1 test) New FireFighters are in-rolling in NSFD "mini Academy"
- C. Newest Firefighters Learning their gear & rigs
- D. Introducing new FF's to our rigs & equipment.
- E. Wildland 2 acre hike, pulling 1000 ft of hose, up & down rough terrain.
- \*MUTUAL Fire Dept's Training: FSD-Oct. 19<sup>th</sup> & 20<sup>th</sup> FIRE CONTROL III by Ft Irwin FD & SBCounty FD \*CALL VOLUME & RESPONSE:
- (36) Calls in the month of AUGUST
- (7) Missed calls- (Mutual-Aid Received by MCLB & Desert Amb. in our absents)
- (2) MUTUAL-AID GIVEN from Newberry Springs FD
- (312) Calls To Date as of 09/19/24
- \*BP393- 8/16/24 Took skid off of truck (waiting on pink slip/proof of title)
- \*E392R-7/3/24 Unit is up & running after installing new batteries.
- \*E392- DOT Inspection 7/1/24-gauges leaking fluid, electric siren is out, tire rubbing on steering box, hydraulic pressure line cracked, pump pack leaked during "dry Vac test", B service fluids & filter needed. 7/8/24 B service was completed, & pulled oil sample for lab. Changed all fluids. Replaced hydraulic lines for cab lifting ram line. 7/11-found when making hard right /left turns, right tire rubs the 6" steel stop bolts. Adjustment completed. Left side steering box pittman arm rubbing, now fixed from rubbing on front rubber discharge hose. Removed bad electric siren box to be replaced. 7/18 oil labs came back perfect. 8/5- installed new master pump drain assembly. Replaced (2) 3" pump panel gauges. 8/6/24- NFPA Annual pump test "PAST!!"
- \*WT392- air conditioner went out, radio was fixed. (will be fixed in-house after parts are purchased)
  \*STATION 392: "Bunking Quarters & Station 392- as of 08/07/24 we are at the mercy of Edison again, were waiting on their utility pole & transformer to be installed, for RoseLove Elect. to complete the job.

### \*EVENTS/ACTIVITIES/GRANTS:

A. AFG-FY2021-funds were disbursed twice. Once in February 2024 but had the wrong bank account #. After weeks of a lot of call & emails, still have not received the \$\$ to our bank BUT FEMA has record that the check for \$138,486.05 has been deposited into our accounts. Flagstar bank has no records of this amount. As of 9/19/24 I still haven't gotten any further along finding this money. I have left emails to all supervisors at each company beside our bank as I am not on the account to ask questions;

### \*PUBLICE COMMENTS/REQUEST:

I was asked by a community member, Ted Stimfel. Mr Stimfel would like to know if there is a way that the solar companies could have some kind of "Community Ajert System" Inside the Lithium Battery containers, to alert the community members if the batteries were to catch fire.

As 9/16/24 Clearway will get back to us about a question asked re "alert system in the Lithium Battery cases for the public"