Newberry Springs FD


Newberry Springs, CA

This report was generated on 7/24/2018 1:55:23 AM



Major Incident Types by Month for Date Range

Start Date: 06/01/2018 | End Date: 06/30/2018



Fire	Good Intent Call	Rescue & Emergency Medical Service Incident	Service Call

INCIDENT TYPE	JUN	TOTAL
Fire	3	3
Good Intent Call	7	7
Rescue & Emergency Medical Service Incident	12	12
Service Call	2	2
Total	24	24

NSFD REPORT JUNE 2018

- *TRAINING: 12 hours of "Wildland/ Progressive Hose-lays" on Thursday nights.
- *E392: Major repair- 5/18th WT392 had trouble starting. Miller drove it to American Towing 5/23rd. ECM had been replaced, picked up WT392 6/23rd & back in service.
- *County Brush Patrol will be signed over to Newberry Fire/CSD 7/24th, & American Tow will pick up Same day, in San Bernardino, & repairs will start. Unknown date of completion.
- *ISO: Miller had completed the documents, & have been reviewed. We have a scheduled meeting August 3rd to check off what's on the documents.
- *Radio Antenna: Mr. Chris Nichols had came to Newberry to check out our repeater, due to Calfire's Captain Wilson had advised Mr.Nichols that there is still minor issues with Newberrys repeater. After testing the repeater again, the repeater system tested perfect. He is recommending to Upgrade the antenna to a "higher gain antenna." (approximately 120')
- *Grants: Still in progress. Waiting on final paperwork. (due July 27th)

^{**}NEWBERRY SPRINGS FIRE DEPARTMENT WOULD LIKE TO "THANK YOU" ALL FOR YOUR SUPPORT**



AMERICAN TOWING & RECOVERY, INC. AMERICAN TRUCK REPAIR 2520 E. MAIN STREET BARSTOW CA 92311 760-256-5200 PHONE 760-256-6611 FAX

INVOICE W 4933

Date

//

Date Open

05/23/18

										Page:	1 of 1
Sold	To: 40	3-3299	760			Shi	p To:				101 1
30884	NEWBE	SPRINGS I RRY RD PRINGS	FIRE DE		USA						
Writt	en By	Terms		Time 14:23:01	Customer Po #	# #	Prom	nised	760-4	Phone 03-3299	Ship Via
Unit # VT392		Plate # 1007517	Year 1999	Make FREIGHTLINER	Model FL80	Milea 20550/0.0	ge/Hrs	1FV6JJC	VIN BOYHB	73322	Engine C7
Qty				Descript	ion					Price	Amount
	TROUBL ECM FAI T/S. FOU REMOVI COMMU MANUFA	E STARTIN LED IND ECM H ED ECM . FL NICATION V	G. AD FAILE LASHED WAS FOL IAD NO F	D INTERNALLY. N NEW ECM AND PI IND TO TRANSFE	COMING ON, AND E TO COMMUNICATION ROGRAMMED UNIT . R OPTIONS TO NEW NS INDIVIDUALLY . T	I WITH EC NO ECM .				107.00	535.
	CAT10R		- U .	ECM						3000.39	3000.
										SubTotal	3535
		_OW		FOUND FREON L	OW IN SYSTEM . CHA	ARGED A/0	3			107.00	
1.000	ZZOR-13	34		R-134A FREON						12.93	12.
										SubTotal	119
OVERYIN	(C. hereby ex	pressly disclaims	all warranties	either expressed or implied,	by the Manufacturer, if any. The s including any implied warranty or nor authorizes any other person t	merchantability	or fitness			rts bor	3013. 642.
nection with	the sale of th	nese parts, and/or	accessories.	PAYMENT FOR WORK ORD	DERS AND INVOICES ARE DUE NDE. 60 Day Limited Warranty on	UPON RECEIP		ALL CURREN	Т	oor	32.
nk you for y	our business	and we look forwa	ard to serving	ou again.							
										ıb Total ıles Tax	3687. 233.
id by									T	OTAL	3920.9